



	HTC-P2P 90mm M12
	Adapter M12 SW19 Offset
	SIW 22T-A SIW 6AT-22 $T_{max} = 500Nm$

Preparation of the wood surface. The wood must be clean and dry. A brush is used to clean the surface. The moisture content must be $\varphi < 18\%$. Safety icons indicate: no eyes, no liquids, and no dust.

A 1

max. 5mm
0mm
max. 20mm

A 3

Adapter M12 SW19 Offset

A 2

180mm

A 4a


93mm-105mm

A 2

KG < 1.5t
KG 1.5t-3t
180mm

A 4b

SIW 22T-A
SIW 6AT-22



Optional

